

NTSB National Transportation Safety Board

Office of Marine Safety

Athena 106
West Cote Blanche
Bay, Louisiana
October 12, 2006

DCA07MM001

Athena 106



USCG Photo





NTSB

NTSB Investigation

- Morgan Turrell, IIC
- Brian Curtis, Engineering
- Liam LaRue, Survival Factors
- Rod Dyck, Pipeline Operations
- Chuck Koval, Pipeline Operations
- Charlotte Cox, Writer/Editor



NTSB Staff

- Christy Spangler, Animation Lab
- Alice Park, Animation Lab
- Mitch Garber, M.D., Medical Officer
- Matt Fox, Materials Specialist
- Don Eick, Weather
- Keith Holloway, Public Affairs
- Mike Brown, Office of Safety Recommendations



Parties

- United States Coast Guard
- OSHA
- NOAA
- Louisiana Dept. of Natural Resources
- Chevron, U.S.A.
- Gulfport Energy
- Athena Construction
- Central Boat Rentals



Safety Issues

- Failure to use safety devices
- Limited oversight of vessels not subject to inspection




Presenters

- Overview
 - Morgan Turrell
- Failure to use safety devices
 - Brian Curtis
- Limited oversight of vessels not subject to inspection
 - M. Turrell



Vessels Involved

- Athena 106
- IBR-234
- Miss Megan






Athena 106






Athena 106




IBR-234 and Miss Megan














Ruptured Pipeline






Emergency Response

- USCG
- St. Mary and Iberia parishes
- Louisiana Dept. of Wildlife and Fisheries
- Local volunteer fire departments
- Nearby vessels





Pipeline Shutdown





Injuries

Type of	Athena	Miss	Total
Injury	106	Megan	
Fatal	4	1	5
Serious	0	1	1
Minor	1	0	1
Missing	1	0	1
Total	6	2	8



Tests and Research

- Sonar survey
- Spud winch examination
- Material analysis of pipe





NTSB